


Measuring Tool for Buckle Band

1. Cut measuring tool along dotted line
2. Measure minimum wrist circumference
3. Measure maximum knuckle circumference

Size	Min Wrist	Max Knuckle
Small	5-1/4"	8-1/2"
Medium	5-3/4"	9"
Large	6-3/4"	9-3/4"
X-Large	7"	10-3/4"



Tips

- Measure up if in between sizes.
- Use a flexible measuring tape, if available.